Revision: 0.0 Date: July 1999

12.0 DATA VALIDATION PROCEDURES

12.0.0.1. As described in Section 3.0, the quality of the field and analytical data shall be

evaluated using the PARCC parameters, which are quantitative and qualitative statements

that describe data quality. The PARCC parameters shall be used to determine whether

the data quality objectives for any given project have been met by comparing QC sample

results and standard procedures with acceptance criteria established for a specific project.

The PARCC parameters that shall be used for data evaluation are defined in Section 3.0.

Data assessment will be conducted in accordance with Q4/G-9 (January 1998) and as

described in the project specific work plan.

12.1 FIELD DATA

12.1.0.1. Field measurement data shall be assessed by the Prime Contractor's QAO or

designee. Although field data are considered screening level, some field data will be used

definitively (lithology data, pH data, groundwater elevation measurement data, etc).

There shall be no formal data validation for screening data, which also includes field data;

however, the field data shall be evaluated qualitatively in terms of the PARCC parameters

as described in Section 3.0 and in Section 9.0. Data shall be assessed in accordance with

QA/G-9 (January 1998) and as described in the project specific work plan.

12.2 LABORATORY DATA

12.2.0.1. Definitive data shall be validated by the Prime Contractor based on the

assumption that the samples were collected, handled, and analyzed according to the

project-specific work plans and this QAPP. The data reviewer shall identify any data

omissions or data that do not meet the quality control criteria. During the validation

process, the reviewer also shall interact with the laboratory to correct any data

deficiencies. Decisions to repeat sample collection or analyses shall be made by the Hill

12-1

Hill AFB Basewide QAPP

Revision: 0.0 Date: July 1999

AFB project manager based on whether the DQOs were met. At a minimum, an

assessment of the data, shall be conducted to determine if data parameters, including

standard deviation and variance are in accordance with the values estimated in the

development of the DQOs and sampling plan. Results of the data validation shall be

presented in an appendix to the report that summarizes sampling results.

12.2.1. Laboratory Data Validation Procedures

12.2.1.1. Principles used for data validation outlined in the U.S. EPA Contract

Laboratory Program National Functional Guidelines for Organic and Inorganic Data

Review (Functional Guidelines) (U.S. EPA, February 1994) will be used as a basis for

validation of definitive data. For all data from those methodologies not included in the

Functional Guidelines, data validation shall be based on the results of QC sample

analysis, sample holding time evaluation, and the basic principles for data validation

outlined in the Functional Guidelines (e.g., method blank contamination). The QC data

used for definitive data validation are listed in Table 3-4; Table 3-5 defines how the QC

samples shall be used to assess PARCC parameters. In addition, the instrument

calibration logs and injection logs shall be reviewed for compliance with this QAPP and

the analytical methods.

12.2.1.2. Based on the data validation, the Prime Contractor shall apply any other data

qualification flags as deemed appropriate. The data qualification flags are shown on

Table 12-1. For example, a matrix spike sample would be qualified by the laboratory if

there was matrix interference during analysis, while the Prime Contractor would apply the

final qualifying flag to the data for the parent sample. The data qualifiers that shall be

used are listed in Table 12-1.

12-2

TABLE 12-1 INDEPENDENT REVIEW DATA QUALIFIERS

Qualifier	Description
В	Analyte is detected in an associated blank.
UB	Analyte is not detected at or above the indicated concentration due to blank contamination.
UK	Analyte is not detected at or above the indicated concentration based on the data validation.
UJ	Possible false negative result due to related QC problems.
J	Result is estimated based due to associated QC problems.
R	Data are considered unusable based on the results of the data validation and/or field procedures evaluation.